




Test 0 unstable

Beta development notes

v2.8 hangs after 100-1500 seconds. (issue with GY-MCU680 need PS pin to be soldered to work with sensor using i2c)



Only two multiplexers



SHT2	SHT3	BME+	Si7x	HDCx	SHT8
SHT25	SHT35	BME680	HTU21d		
SHT21	SHT35	BME680	Si7021-4		
SHT21	SHT31-2	BME280	Si7021-3		

SHT21-c	SHT31-2	BME280	Si7021-3		
SHT21-c	SHT31	BME280	Si7021-2		
SHT20	SHT31	DHT12	Si7021-2		
SHT20	SHT30	DHT12	Si7021		
SHT20	SHT30	DHT12	Si7021		

No hangs on two muxes for 2 hours test run