


XINTEST HT-501





Set Parameters

✕

Address(1-254):

Serial Number:

Test Name:

Total Records: ▾

Interval: ▾

1Minutes 40Seconds

Temperature Unit: ☒ °C(Celsius) ☐ °F(Fahrenheit)

Temperature Alarm: Low °C High °C

Humidity Alarm: Low %RH High %RH

CO2 Alarm: High PPM

Current Time:

☐ Manual ☒ Immediate

Default

OK

Cancel