


XINTEST HT-501





Communication - Communication Tool

FileCommunicationViewHelp

Communication

Auto RefreshInterval: 1sRefreshSet TimeRead ParamSet ParamData DownloadStop Recording

10-08-2081 19:01:49Rec: 11

L0

H40

24.9 °C

L10

H95

37.6 RH %

CO2

H2000

608 PPM

Setting Parameters

Content

Address1

Serial Number

Test Name

Setting Time03-19-2018 10:10:13

Total Records100

Record Interval1 sec

Immediately/ManualImmediately

Temperature AlarmL:0 H:40 °C

Humidity AlarmL:10 H:95 %RH

CO2 Alarm2000 ppm

Start Time03-19-2018 10:10:13

Record Parameters

Content

Address1

Serial Number

Test Name

Setting Time03-19-2018 10:10:13

Total Records100

Record Interval1 sec

Immediately/ManualImmediately

Temperature AlarmL:0 H:40 °C

Humidity AlarmL:10 H:95 %RH

CO2 Alarm2000 ppm

Start Time03-19-2018 10:10:13

Test Records11

TEMP AlarmNONE

HUMI AlarmLow(RH) High(RH)

CO2 Alarm

Ready

Meter: ConnectedCAPNUMSCRL

Set Parameters

✕

Address(1-254):

Serial Number:

Test Name:

Total Records: ▾

Interval: Sec ▾

1Minutes 40Seconds

Temperature Unit: ☒ °C(Celsius) ☐ °F(Fahrenheit)

Temperature Alarm: Low °C High °C

Humidity Alarm: Low %RH High %RH

CO2 Alarm: High PPM

Current Time:

☐ Manual ☒ Immediate

Default

OK

Cancel