HDO5 inside

Board MY-2195 V02 20210928

| component	model
MCU	erased
t/RH Sensor	unknown (MY-TH01)
CO2 Sensor	absent
TVOC Sensor	TPM-300A-V2.2x
LED Controller	TM1680
Battery	DST 18650 3.7v 1200mAh

there is a connector for the IR sensor on the board but no sensor is connected.

t/RH Sensor

Chip with marks erased

LED Driver

battery

TPM-300A-V2.2 Air Quality VOC Module

Module model	TPM-300A-V2.2

Sensor model	TP-401T/P
Detect gas	Ammonia, hydrogen, alcohol, carbon monoxide, methane and other organic volatile gases; cigarettes, wood, paper burning smoke, lampblack, etc.
URL	http://www.szdovelet.com/product/html/?167.html