

Test 0 Serial plotter incl HTU21d

Humidity sensors tester v3.1					
SHT2	SHT3	BME+	Si7x	HTU2	SHT8
55.10 24.04	54.88 23.93	52.54 24.25	54.44 24.06	50.19 24.10	46.17 24.49
52.92 24.05	54.38 24.13	53.88 24.20	61.71 24.04	49.58 24.25	44.08 24.70
52.59 24.26	53.54 24.28	48.85 24.85	54.62 24.24	48.91 24.62	52.56 24.55
53.63 24.32	56.22 24.47	49.36 24.71	53.85 24.21	46.63 24.53	52.21 24.37
53.37 24.27	54.67 24.43	48.34 25.04	50.25 24.32	48.18 24.88	52.27 24.35
52.88 24.28	54.78 24.41	51.53 25.35	51.24 24.38	46.91 24.62	52.34 24.43
53.15 24.30	53.78 24.43	49.63 24.75	50.18 24.28	46.47 24.70	53.37 24.64
53.88 24.15	54.27 24.29	49.40 25.02	0.00 24.32	46.43 24.88	53.12 24.62
https://wiki.liutyi.info/					

