


Test 2. Sensors in a freezer 1

- Sensor in a freezer. Humidity trend
- Sensor in a freezer. Temperature trend
- Sensor in a freezer. Humidity trend fragment
- Sensor in a freezer. Temperature trend fragment


SHT2	SHT3	BME+	AHT1	HDCx	SHT8
SHT25	SHT35	BME680	AHT10	HTU21d-3	BME680-2
SHT21	SHT35	BME680	AHT10	HTU21d-2	BME680-2
SHT21	SHT31-2		AHT10	HTU21d-2	SHT31-A
SHT21-c	SHT31-2		AHT10	HTU21d	SHT85
SHT21-c	SHT31		AHT10	HTU21d	SHT85
SHT20	SHT31		AHT10	HTU21d	SHT85
SHT20	SHT30		AHT10	HTU21d	SHT32-2
SHT20	SHT30		AHT10	HTU21d	SHT32-2

Found mistakes in my BME280 code related to subzero temperatures so excluding them from this test,


Sensor in a freezer. Humidity trend



Sensor in a freezer. Temperature trend



Sensor in a freezer. Humidity trend fragment



Sensor in a freezer. Temperature trend fragment

TEMPERATURE SENSORS IN FREEZER (1)

SHT25 SHT21 SHT21 SHT21-CJMCU SHT21-CJMCU SHT20 SHT20 SHT20 SHT35 SHT35 SHT31-2 SHT31-2
SHT31 SHT31 SHT30 SHT30 BME680-1 BME680-1 SHT31-A SHT85 SHT85 SHT85 SHT31-2
AHT10 AHT10 AHT10 AHT10 AHT10 AHT10 AHT10 HTU21d-3 HTU21d-2 HTU21d-2 HTU21d
HTU21d HTU21d HTU21d HTU21d BME680-2 BME680-2

